

## 10x // SLIDING THERMAL INSTALLATION STEPS

- 1) Collect all necessary items near installation area and be sure that all items are visible.
- 2) Connect upper rail and side posts with corner connection plate as U shape and make the fixation of skeleton at project place.
- 3) Place side plastics of bottom rail and put between the side posts. Before fixation be sure that side posts and bottom rail touch each others and in balance. When you sure, make the fixation of bottom rail through the ground.
- 4) Start to place glass panels as start of outside through the inside as one by one. Be sure that first and last panels should be with lock and at right direction and middle ones will be standard panels.
- 5) After panels assembly completed, make the fixation of winders. Standard arm should be placed inner side and lockable arm should be placed outer area in terms of safety.
- 6) As last make the panel height adjustment through the bottom wheels while turning screw at intended direction. Make sure that two panels connect each other as 90 degree and in balance.
- 7) Apply the silicone fixation to provide water thightness. Silicone should be applied outer area for side posts upper rail and inner area for bottom rail .

## LARİBA TEKNOLOJİ YATIRIM A.Ş.

1-Collect all necessary items near installation area and be sure that all items are visible.











